APPENDIX C – Potential risks or threats report

Fulwood and Douglas Avenue Conservation Area

Article 4 (2) Direction restriction	Current situation	Implications of Article 4(2) Direction	Risks associated with Art 4 (2) High/medium/low/NA
Erection, alteration or removal of a	242 Hesketh Lane has two tall	These chimneys should be	Low – effect on value
chimney on dwelling or building in curtilage.	feature brick chimneys, one with intact chimney pots.	retained	probably minimal
	244 Hesketh Lane has two smaller intact brick chimneys complete with chimney pots.	These chimneys should be retained	Low - effect on value probably minimal
Enlargement, improvement or other alteration of a dwelling	242 Hesketh Lane – no extensions at present. Some UPVC at first floor level, but feature bow/bay windows on ground floor remain wooden. Wooden front door.	Further loss of original wooden windows should be resisted. Where they have been lost, we should seek improvements in any replacements, using originals elsewhere within the area as the basis.	Some loss has already occurred reducing the risk from further changes. Effect on value minimal.
	244 Hesketh Lane – no extensions at present. Most windows at front have been replaced with UPVC but some ground floor windows retain leaded light detailing to upper lights. UPVC front door.		Low due to changes already undertaken.
Alteration of dwelling roof	242 Hesketh Lane has an original 'rosemary red' tile roof.	Original roof coverings should be retained.	Low to medium.

Article 4 (2) Direction restriction	Current situation	Implications of Article 4(2) Direction	Risks associated with Art 4 (2) High/medium/low/NA
	244 Hesketh Lane has an original slate roof.	Original roof coverings should be retained.	Low to medium.
Erection/construction of a porch outside any external door	242 Hesketh Lane has an original flat-roofed porch to the side elevation entrance to the property. No porch to the front entrance.	Addition of a porch would not be ruled out, providing the design was sympathetic.	Low
	244 Hesketh Lane has an original porch to the front elevation.	244 has an existing porch, therefore this shouldn't be too much of an issue.	Low – already has a porch
Provision within curtilage of a building, enclosure, swimming or other pool incidental to the enjoyment of the dwelling or required for the maintenance, improvement or alteration of building or enclosure	242 Hesketh Lane currently has a modest garage set to the side/rear of the property. 244 Hesketh Lane has a number of small wooden outbuildings.	Provision of subservient buildings not ruled out – dependent on location and scale.	Low – unlikely to be an issue as Article 4 controls works on frontage.
Creation of hard surfaces within the curtilage of a house incidental to its enjoyment	242 Hesketh Lane has a substantial paved area to the front and side of the property sufficient for several cars screened by a front hedge and garden border which acts as a landscaping buffer.	Both properties have a substantial amount of hard standing – sufficient for providing off-road parking for a family, taking into consideration the size of the properties. Would resist further loss of garden areas which provide some degree of a garden setting.	Low – both properties already have substantial drives.

Article 4 (2) Direction restriction	Current situation	Implications of Article 4(2) Direction	Risks associated with Art 4 (2) High/medium/low/NA
	244 Hesketh Lane has a block		Low – both properties
	paved driveway to the front and		already have substantial
	side of the property, sufficient for 2 cars.		drives.
Installation, alteration or replacement	242 Hesketh Lane – none in	Restrictions already exist via	NA
of satellite antenna on house or	evidence on front or side	Planning on front elevations in	
curtilage	elevations.	Conservation Areas	
	244 Hesketh Lane - none in		
	evidence on front or side		
	elevations.		
Erection or demolition of gates,	242 Hesketh Lane – Hedge to	Encourage retention of front	Low
fences, walls or other means of enclosure within the curtilage	front boundary.	hedge.	
S	244 Hesketh Lane – front	Existing concrete and wood panel	
	boundary partially fenced with	fence a negative feature. Would	
	wide opening for vehicle access	encourage replacement with	
		hedging or simple low wood	
		panel fence.	
Painting of a dwelling or building or	The exterior roughcast of both	Encourage retention of existing	Low
enclosure within the curtilage	properties has been painted	colour palette.	
	white/off white – an appropriate		
	colour.		

Junction Lane Conservation Area

Article 4 (2) Direction	Current situation	Implications of Article 4(2)	Risks associated with Art 4(2)
restriction		Direction	High/medium/low/NA
Creation of hard surfaces within the	Both 1a and 1b Junction Lane have	Both properties have a substantial	Low
curtilage of a house incidental to its	a paved area to the front and side	amount of hard standing –	
enjoyment	of the property sufficient for	sufficient for providing off-road	
	approx. 2 cars. No.1b also has a	parking for a family, taking into	
	garage.	consideration the size of the	
		properties. We would resist	
		further loss of garden areas which	
		provide some degree of a garden	
		setting.	
Erection or demolition wall, gates	Surviving garden wall feature –	This wall with balustrade feature	Low – minimal effect on value
or fences, or other means of	this is the remaining evidence of	should be retained.	
enclosure within the curtilage	the large pleasure gardens which		
	originally belonged to no.1		
	Junction Lane.		